


## EZBarcode - Setup

Just scan each of the barcodes in the order listed to the right.

1.



Reset Options

2.



Reset Macros

3.



9600 Baud

4.



Output All Mag Stripe Data  
→ Don't Output ← Output

5.



Disable Track II  
→ Enable ← Disable

6.



Return After Bar Code  
→ Enable ← Disable

7.



Full ASCII Code 39  
→ Disable ← Enable

8.



Enter/Exit Macro Mode

9.



Postamble

10.



Carriage Return (\$M)

11.



Enter/Exit Macro Mode